

جدول راهنمای انتخاب دور و گشتاور

راهنمایی :
 : kw Hp
 rpm : دور اولیه و ثانویه n2 n1
 : T n/m
 : D mm
 : M وزن تقریبی دستگاه با الکترو موتور ۳ن kg

M	D	T	n2	n1	KW	HP	type
21	28	135	16	700	0.25	0.33	G1
21	28	108	20	900			
18	28	86	25	900			
18	28	70	31	1400			
18	28	54	40	1400			
18	28	43	50	1400			
18	28	34	63	1400			
18	28	27	80	1400			
18	28	21	100	1400			
18	28	18	125	1400			
18	28	13	160	1400			
18	28	10	200	1400			
18	28	9	250	1400			
18	28	7	300	1400			
18	28	5	400	1400			
18	28	103	31	1400			
18	28	80	40	1400			

18	28	64	50	1400	0.37	0.5	G1
18	28	50	63	1400			
18	28	40	80	1400			
18	28	32	100	1400			
18	28	25	125	1400			
18	28	20	160	1400			
18	28	16	200	1400			
18	28	13	250	1400			
18	28	11	300	1400			
18	28	8	400	1400			
20	28	75	63	1400	0.55	0.75	G1
20	28	59	80	1400			
20	28	47	100	1400			
20	28	38	125	1400			
20	28	30	160	1400			
20	28	24	200	1400			
20	28	19	250	1400			
20	28	16	300	1400			
20	28	12	400	1400			
23	28	102	63	1400			
23	28	81	80	1400			
23	28	64	100	1400			
23	28	52	125	1400			

23	28	40	160	1400			
23	28	32	200	1400			
23	28	26	250	1400			
23	28	21	300	1400			
23	28	16	400	1400			
26	28	95	100	1400	1.1	1.5	G1
26	28	76	125	1400			
26	28	59	160	1400			
26	28	47	200	1400			
26	28	38	250	1400			
26	28	32	300	1400			
26	28	24	400	1400			